



Commercial Vehicle Auctions Ltd.

PJ20ZHX

CN: W1V9106332P254147

Photos



General Details

MERCEDES-BENZ SPRINTER 314 CDI

Vat Status: Commercial (plus Vat)

Mileage	216,228 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	31/08/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	31/08/2020	2020	Yes



Valid MOT
Expires: 18/07/2025



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	

Photos



Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Number Plate Front	Missing	Replace	Replace
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Unclassified	Substantial Accident Damage	Report Only	Report Only (Grade)

Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Door nsr	Chipped	Multiple Chips	Refinish
Badgedecal Rear	Missing	Replace	Replace
Door nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Seat Base Cover osf	Holed	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3

D3

C2

M

Damage Assessment



Chipped
Multiple
Chips
Refinish



Missing
Needs
Replaced
Replace



Scratched
Over
100mm
Thru Paint
Refinish



Dented
Over
30mm
Repair
and
Refinish



Substantial
Accident
Damage
Report
Only
Report
Only
(Grade)



Dented
Over
30mm
Repair
and
Refinish



Chipped
Multiple
Chips
Refinish



Missing
Needs
Replaced
Replace



Dented
Over
30mm
Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



Door osf

Dented

Over
30mm

Repair
and
Refinish



**Seat
Base
Cover
osf**

Holed

Over 3mm

Replace



**Seat
Base
Cover
nsf**

Soiled

Heavy

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.