



Commercial Vehicle Auctions Ltd.

PJ20SZP

CN: W1V9106332P251933

Photos



General Details

MERCEDES-BENZ SPRINTER 314 CDI AUTO 9G-TRONIC

Vat Status: Commercial (plus Vat)

Mileage	210,693 miles	Miles Warranty	Yes
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	18/08/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	18/08/2020	2020	Yes



Valid MOT
Expires: 17/08/2025



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels

Alloy	OSF	3mm-5mm
Steel ✓	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm


Interior Condition

Carpets	Poor
Upholstery	Average
Seats	Average
Odour	Average
Comments	

Service History

Service	No
History	
Stamps	

Photos



Damage Lines

Component	Condition	Severity	Repair
Carpets Front	Torn	Over 10mm	Replace
Sill os	Scratched	Over 25mm Thru Paint	Refinish
Bonnet	Dented	With Paint Damage	Repair and Refinish
Bumper Front Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Tailgate	Dented	Over 30mm	Repair and Refinish
Badgedecal Rear	Missing	Replace	Replace
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door Moulding nsf	Scuffed (Unpainted)	Over 100mm	Smart Repair
Door nsf	Dented	Over 30mm	Repair and Refinish

Wing nsf	Dented	With Paint Damage	Repair and Refinish
Roof	Rusted	Over 5mm	Refinish

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

K
Crack/Torn

M
Missing

SC
Scuff

Damage Assessment					
	Carpets Front Torn Over 10mm Replace		Sill os Scratched Over 25mm Thru Paint Refinish		Bonnet Dented With Paint Damage Repair and Refinish
	Bumper Front Moulding Scuffed (Unpainted) Over 100mm Smart Repair		Wing osf Chipped 1 To 5 Smart Repair		Door osf Dented Between 10mm + 30mm Smart Repair
	Tailgate Dented Over 30mm Repair and Refinish		Badgedecal Rear Missing Needs Replaced Replace		Qtr Panel nsr Dented With Paint Damage Repair and Refinish
	Door nsr Dented With Paint Damage Repair		Door Moulding nsf Scuffed (Unpainted) Over		Door nsf Dented Over 30mm Repair



and
Refinish



100mm
Smart
Repair



and
Refinish



Wing nsf

Dented

With Paint
Damage

Repair
and
Refinish



Roof

Rusted

Over 5mm

Refinish

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.