



Carr Hill Industrial Estate  
Doncaster  
South Yorkshire  
DN4 8DE  
Tel: 01302 732600  
Email: enquiries@cva-auctions.co.uk

## Commercial Vehicle Auctions Ltd.

LC22JUE

CN: VF7VBYHRMN7019252

### Photos



### General Details

CITROEN DISPATCH 1000 1.5 BLUEHDI  
ENTERPRISE PRO 100PS

Vat Status: Commercial (plus Vat)

Mileage	49,172 miles	Miles Warranty	No
Colour	Black	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	30/04/2022	Engine Size	
Body Type			

### Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
	30/04/2022	2022	Yes



Valid MOT  
Expires: 29/04/2025



No V5

### Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Air	Yes	Central	Yes
Conditioning:		Locking:	
Cruise Control	No	Phone Kit:	BlueTooth
		Metallic	No
		Paint:	

### Tyres & Wheels

Alloy	OSF	3mm-5mm
Steel ✓	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm

### Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Odour	Average
Comments	

### Service History

Service	No
History	
Stamps	



Damage Lines

Component	Condition	Severity	Repair
Sill os	Dented	Between 10mm + 30mm	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Cracked	Over 25mm	Replace
Wing osf	Dented	With Paint Damage	Repair and Refinish



Door osf	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Tailgate	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Scratched	Over 25mm Thru Paint	Refinish
Wing osf	Dented	Between 10mm + 30mm	Smart Repair
Screen Front	Cracked	Replace	Replace

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**D2**  
Dent/damage 30-100mm

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

**X**  
Req Replacement

**SC**  
Scuff

Damage Assessment

	<p><b>Sill os</b></p> <p>Dented</p> <p>Between 10mm + 30mm</p> <p>Smart Repair</p>		<p><b>Bonnet</b></p> <p>Chipped</p> <p>1 To 5</p> <p>Smart Repair</p>		<p><b>Bumper Front</b></p> <p>Cracked</p> <p>Over 25mm</p> <p>Replace</p>
	<p><b>Wing osf</b></p> <p>Dented</p> <p>With Paint Damage</p> <p>Repair and Refinish</p>		<p><b>Door osf</b></p> <p>Scratched</p> <p>Over 25mm Thru Paint</p> <p>Refinish</p>		<p><b>Qtr Panel osr</b></p> <p>Scratched</p> <p>Over 25mm Thru Paint</p> <p>Refinish</p>
	<p><b>Bumper Rear Moulding</b></p> <p>Scuffed (Unpainted)</p> <p>Over 100mm</p> <p>Smart Repair</p>		<p><b>Tailgate</b></p> <p>Dented</p> <p>With Paint Damage</p> <p>Repair and Refinish</p>		<p><b>Qtr Panel nsr</b></p> <p>Dented</p> <p>With Paint Damage</p> <p>Repair and Refinish</p>



**Door nsr**  
Dented  
With Paint  
Damage  
Repair  
and  
Refinish



**Door nsf**  
Scratched  
Over  
25mm  
Thru Paint  
Refinish



**Wing osf**  
Dented  
Between  
10mm +  
30mm  
Smart  
Repair



**Screen  
Front**  
Cracked  
Needs  
Replaced  
Replace

**Comments**

WINDSCREEN NEEDS REPLACED

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.