



Commercial Vehicle Auctions Ltd.

MX69AVC

CN: VF1VA000762549337

Photos



General Details

RENAULT MASTER LL35 2.3 DCI BUSINESS

Vat Status: Commercial (plus Vat)

Mileage	145,290 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	27/09/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	27/09/2019 YOM	2019 Runner? Yes/No Yes



Valid MOT
Expires: 26/09/2025



No V5

Extras

Stereo:	HDD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	Yes	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels


Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Scratched	Over 25mm Thru Paint	Refinish
Bonnet	Chipped	Multiple Chips	Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	Over 30mm	Repair and Refinish
Seat Base Cover osf	Holed	Over 3mm	Replace

Vehicle Splat



Splat Key

- S3**
Scratch/Paint defect 100m +
- D3**
Dent/damage 100mm +
- C2**
Multiple Chips
- K**
Crack/Torn

Damage Assessment



Bonnet

Scratched
Over
25mm
Thru Paint
Refinish



Bonnet

Chipped
Multiple
Chips
Refinish



Wing nsf

Dented
Over
30mm
Repair
and
Refinish



Wing nsf

Scratched
Over
25mm
Thru Paint
Refinish




Bumper Front

Scratched
Over
100mm
Thru Paint
Refinish



Door Mirror Assy nsf

Broken
Needs
Replaced
Replace



Qtr Panel nsr

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Qtr Panel osr

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door osf

Dented
Over
30mm
Repair
and
Refinish



Seat Base Cover osf

Holed
Over 3mm
Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.