



Carr Hill Industrial Estate
Doncaster
South Yorkshire
DN4 8DE
Tel: 01302 732600
Email: enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.

MX69AUM

CN: VF1VA000362689546

Photos



General Details

RENAULT MASTER LL35 BUSINESS 2.3 DCI 130PS

Vat Status: Commercial (plus Vat)

Mileage	198,620 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	11/10/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2019	Yes



Valid MOT
Expires: 11/10/2025



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	Yes	Central Locking:	Yes
Air	Yes	Phone Kit:	No
Conditioning:		Metallic Paint:	No
Cruise Control	No		

Tyres & Wheels

Alloy	OSF	3mm-5mm
Steel ✓	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm




Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Odour	Average
Comments	

Service History

Service History	No
Stamps	

Photos



Damage Lines

Component	Condition	Severity	Repair
Sill os	Scratched	Over 25mm Thru Paint	Refinish
Bonnet	Rusted	Over 5mm	Refinish
Wing osf	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish

Tailgate	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Rusted	Over 5mm	Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Bumper Front	Insecure	Action Required	Smart Repair
Roof	Rusted	Over 5mm	Refinish

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D2
Dent/damage 30-100mm

R
Rust

Damage Assessment

	Sill os Scratched Over 25mm Thru Paint Refinish		Bonnet Rusted Over 5mm Refinish		Wing osf Dented Over 30mm Repair and Refinish
	Door osf Dented Between 10mm + 30mm Smart Repair		Qtr Panel nsr Dented With Paint Damage Repair and Refinish		Tailgate Dented Over 30mm Repair and Refinish
	Qtr Panel nsr Rusted Over 5mm Refinish		Door nsf Dented With Paint Damage Repair and Refinish		Bumper Front Insecure Action Required Smart Repair
	Roof Rusted Over 5mm Refinish				



Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.