



Commercial Vehicle Auctions Ltd.

BD21HNK

CN: VF3YCBNFC12S49405

Photos



General Details

PEUGEOT BOXER 335 2.2 BLUEHDI
PROFESSIONAL 140PS

Vat Status: Commercial (plus Vat)

Mileage	126,423 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Half
Reg Date	30/04/2021	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2021	Yes



Valid MOT
Expires: 16/05/2025



V5 with CVA

Extras

Interior:	Cloth	Electric	2
Sat Nav:	Yes	Windows:	
Air	Yes	Central Locking:	Yes
Conditioning:		Phone Kit:	No
Cruise Control	Yes	Metallic Paint:	No

Tyres & Wheels




Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition


Carpets	Average
Upholstery	Average
Seats	Average
Odour	Average
Comments	

Service History

Service History	No
Stamps	



Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
A Post os	Dented	Over 30mm	Repair and Refinish
B Post os	Dented	With Paint Damage	Repair and Refinish
Door Mirror Assy osf	Broken	Replace	Replace
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Insecure	Action Required	Smart Repair
Panel Rear	Cracked	Replace	Replace
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel Trim ns	Scuffed	Over 25mm	Smart Repair
Bumper Front	Insecure	Action Required	Smart Repair

Damage Assessment					
	Bonnet Chipped 1 To 5 Smart Repair		A Post os Dented Over 30mm Repair and Refinish		B Post os Dented With Paint Damage Repair and Refinish
	Door Mirror Assy osf Broken Needs Replaced Replace		Qtr Panel osr Scratched Over 25mm Thru Paint Refinish		Qtr Panel osr Scratched Over 25mm Not Thru Paint Machine Polish
	Qtr Panel osr Dented Over 30mm Repair and Refinish		Bumper Rear Insecure Action Required Smart Repair		Panel Rear Cracked Needs Replaced Replace
	Qtr Panel nsr Dented Over 30mm Repair and Refinish		Qtr Panel Trim ns Scuffed Over 25mm Smart Repair		Bumper Front Insecure Action Required Smart Repair

Comments

eml on dash

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.