



Commercial Vehicle Auctions Ltd.

LD21KYJ

CN: VF7YCBNFB12S14140

Photos



General Details

CITROEN RELAY 35 ENTERPRISE 2.2 BLUEHDI 140PS

Vat Status: Commercial (plus Vat)

Mileage	114,482 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	31/03/2021	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2021	Yes



Valid MOT
Expires: 28/05/2025



V5 with CVA

Extras

Interior:	Cloth	Electric	2
Sat Nav:	Yes	Windows:	
Air	Yes	Central Locking:	Yes
Conditioning:		Phone Kit:	No
Cruise Control	Yes	Metallic Paint:	No

Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Average
Seats	Average
Odour	Average
Comments	

Service History

Service History	No
Stamps	

Photos



Damage Lines

Component	Condition	Severity	Repair
Bonnet	Rusted	Over 5mm	Refinish
Roof	Dented	Hail - Moderate	Repair and Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Qtr Panel Trim ns	Missing	Replace	Replace

Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Cracked	Over 25mm	Replace
Panel Rear	Dented	Over 2 UpTo 10mm	Smart Repair
Panel Rear	Dented	Over 2 UpTo 10mm	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Dented	Hail - Moderate	Repair and Refinish
Carpets Front	Torn	Over 10mm	Replace

Damage Assessment					
	Bonnet Rusted Over 5mm Refinish		Roof Dented Hail - Moderate Repair and Refinish		Door Mirror Assy nsf Broken Needs Replaced Replace
	Qtr Panel Trim ns Missing Needs Replaced Replace		Qtr Panel nsr Scratched Over 25mm Thru Paint Refinish		Qtr Panel nsr Dented Over 30mm Repair and Refinish
	Bumper Rear Cracked Over 25mm Replace		Panel Rear Dented Over 2 UpTo 10mm Smart Repair		Panel Rear Dented Over 2 UpTo 10mm Smart Repair
	Qtr Panel osr Scratched Over 25mm Thru Paint Refinish		Qtr Panel osr Dented Hail - Moderate Repair and Refinish		Carpets Front Torn Over 10mm Replace

Comments
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.