



Commercial Vehicle Auctions Ltd.

DP19VUE

CN: XLRAEL1500L487824

Photos



General Details

DAF LF 180 EURO 6 7.5 TONNE

Vat Status: Commercial (plus Vat)

Mileage	158,315 km	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	27/06/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Day Cab	Plated Weight	Doors	
Body Length	Axle Combi	4x2	Steering Combi	Rear Susp	Spring
Gears	6 DFR	27/06/2019	YOM	2019	Runner? Yes/No
					Yes



Valid MOT
Expires: 31/10/2025



No V5

Extras



Stereo:	CD	Electric Windows:	2
Interior:	Cloth	Central Locking:	Yes
Sat Nav:	No	Phone Kit:	No
Air Conditioning:	No	Metallic Paint:	No
Cruise Control	Yes		

Interior Condition

Carpets	Good
Upholstery	Poor
Seats	Poor
Odour	
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Wing osf	Scratched	Over 25mm Thru Paint	Refinish
Door Moulding osf	Missing	Replace	Replace
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Panel Front	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door nsf	Scratched	Rusted	Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Qtr Panel Trim ns	Scuffed	Over 25mm	Smart Repair
Door Pad osf	Soiled	Heavy	Replace
Seat Base Cover osf	Torn	Over 3mm	Replace
Dash Warning Lights	Displayed	No Action	Report Only

Vehicle Splat



Splat Key

- S3**
Scratch/Paint defect 100m +
- D3**
Dent/damage 100mm +
- K**
Crack/Torn
- M**
Missing


Damage Assessment



Qtr Panel



Qtr Panel



Door osf



osr
Scratched
Over 25mm Thru Paint
Refinish



osr
Scratched
Over 25mm Thru Paint
Refinish



Scratched
Over 25mm Thru Paint
Refinish



Wing osf
Scratched
Over 25mm Thru Paint
Refinish



Door Moulding osf
Missing
Needs Replaced
Replace



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Panel Front
Scratched
Over 25mm Thru Paint
Refinish



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Door nsf
Scratched
Rusted
Refinish



Door nsf
Dented
Over 30mm
Repair and Refinish



Qtr Panel Trim ns
Scuffed
Over 25mm
Smart Repair



Door Pad osf
Soiled
Heavy
Replace



Seat Base Cover osf
Torn
Over 3mm
Replace



Dash Warning Lights
Displayed
No Action
Report Only



Comments

Ids warning displayed.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.