



Commercial Vehicle Auctions Ltd.

SY73NLA

CN: LSH14J7C1PA119825

Photos



General Details

MAXUS DELIVER 9 2.0 TD 150PS

Vat Status: Commercial (plus Vat)

Mileage	22,235 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	06/10/2023	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2023	Yes



Valid MOT
Expires: 05/10/2026



No V5

Extras

Stereo:	Radio	Electric	1
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF	3mm-5mm
Steel	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Average
Comments	

Service History

Service	No
History	
Stamps	



Damage Lines

Component	Condition	Severity	Repair
Carpets Front	Torn	Over 10mm	Replace
Seat Back Cover nsf	Torn	Over 3mm	Replace
Door Pad nsf	Missing	Replace	Replace
Door Window nsf	Missing	Replace	Replace
Sill os	Scratched	Over 25mm Thru Paint	Refinish
Door Mirror Glass os	Broken	Replace	Replace
Door Mirror Assy osf	Broken	Replace	Replace
Wing osf	Dented	Between 10mm + 30mm	Smart Repair
Door osf	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Bumper Rear Moulding	Scuffed (Unpainted)	UpTo 100mm	Smart Repair
Badgedecal Rear	Broken	Replace	Replace

Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Door nsr	Dented	Over 30mm	Repair and Refinish
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair

Vehicle Splat

Splat Key

S1
Scratch/Paint defect to 30mm

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

K
Crack/Torn

X
Req Replacement

M
Missing

SC
Scuff

Damage Assessment

Carpets Front

Torn

Over 10mm

Replace

Seat Back Cover nsf

Torn

Over 3mm

Replace

Door Pad nsf

Missing

Needs Replaced

Replace

Door Window nsf

Missing

Needs Replaced

Replace

Sill os

Scratched

Over 25mm Thru Paint

Refinish

Door Mirror Glass os

Broken

Needs Replaced

Replace

Door Mirror Assy osf

Broken

Needs Replaced

Replace

Wing osf

Dented

Between 10mm + 30mm

Smart Repair

Door osf

Dented

Over 30mm

Repair and Refinish

Qtr Panel osr

Dented

With Paint

Bumper Rear Moulding

Scuffed

Badgedecal Rear

Broken

Needs

	Damage Repair and Refinish		(Unpainted) UpTo 100mm Smart Repair		Replaced Replace
	Qtr Panel nsr Dented Between 10mm + 30mm Smart Repair		Door nsr Dented Over 30mm Repair and Refinish		Wing nsf Scratched Over 25mm Thru Paint Refinish
	Bumper Front Scratched 25 to 100mm Thru Paint Smart Repair				

Comments
MISSING PANELS ON VEHICLE No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.