



Commercial Vehicle Auctions Ltd.

SY73NLC

CN: LSH14J7C1PA119873

Photos



General Details

MAXUS DELIVER 9 2.0 TD 150PS

Vat Status: Commercial (plus Vat)

Mileage	26,232 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Half
Reg Date	06/10/2023	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2023	Yes



Valid MOT
Expires: 05/10/2026



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	No
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth

Tyres & Wheels

Alloy	OSF Depth	mm
Steel	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Poor
Comments	

Service History

Service History	No
Stamps	


Photos



Damage Lines

Component	Condition	Severity	Repair
Wing Front Arch Extension os	Broken	Replace	Replace
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bumper Front Moulding	Broken	Replace	Replace
Fuel Flap	Missing	Replace	Replace
Qtr Panel nsr	Rusted	Over 5mm	Refinish
Bumper Rear Moulding	Broken	Replace	Replace
Door nsr	Dented	With Paint Damage	Repair and Refinish
Boot Lid	Cracked	Replace	Replace
Bumper Rear Moulding	Broken	Replace	Replace
Qtr Panel osr	Rusted	Over 5mm	Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish


Vehicle Splat



Splat Key

- S2**
Scratch/Paint defect 30-100mm
- D2**
Dent/damage 30-100mm
- D3**
Dent/damage 100mm +
- C2**
Multiple Chips
- X**
Req Replacement
- R**
Rust

Damage Assessment



Wing Front Arch Extension os

- Broken
- Needs Replaced
- Replace



Bumper Front

- Chipped
- Multiple Chips
- Smart Repair



Bumper Front Moulding

- Broken
- Needs Replaced
- Replace



Fuel Flap

- Missing
- Needs Replaced
- Replace




Qtr Panel nsr

- Rusted
- Over 5mm
- Refinish



Bumper Rear Moulding

- Broken
- Needs Replaced
- Replace



Door nsr

- Dented
- With Paint Damage
- Repair and Refinish




Boot Lid

- Cracked
- Needs Replaced
- Replace



Bumper Rear Moulding

- Broken
- Needs Replaced
- Replace



Qtr Panel osr

- Rusted
- Over 5mm
- Refinish



Qtr Panel osr

- Dented
- With Paint Damage
- Repair and Refinish

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.