



Commercial Vehicle Auctions Ltd.

FJ19ZXA

CN: WF0YXXTTGYJR52532

Photos



General Details

FORD TRANSIT CUSTOM 280 2.0TDCI BASE
130PS

Vat Status: Commercial (plus Vat)

Mileage	97,689 miles	Miles Warranty	
Colour	Red	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	19/03/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2019	No



Valid MOT
Expires: 10/04/2025



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central Locking:	Yes
Air	No	Phone Kit:	No
Conditioning:		Metallic Paint:	No
Cruise Control	No		

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Poor
Seats	Poor
Odour	Good
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Fuel Flap	Missing	Replace	Replace
Door Moulding nsf	Broken	Replace	Replace
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel Trim ns	Broken	Replace	Replace
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Lamp osr	Broken	Replace	Replace
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Chipped	Multiple Chips	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Seat Base Cover osf	Torn	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace
Fascia Panel	Scuffed	Over 25mm	Smart Repair

Vehicle Splat



Splat Key

S3
Scratch/Paint defect 100m +
D2
Dent/damage 30-100mm
D3
Dent/damage 100mm +
C2
Multiple Chips
K
Crack/Torn
M
Missing

Damage Assessment



Bonnet
Chipped



Bumper Front
Scratched



Door nsf
Dented



Multiple
Chips
Refinish



Over
100mm
Thru Paint
Refinish



Over
30mm
Repair
and
Refinish




Fuel Flap
Missing
Needs
Replaced
Replace



Door Moulding nsf
Broken
Needs
Replaced
Replace




Qtr Panel nsr
Dented
Over
30mm
Repair
and
Refinish



Qtr Panel Trim ns
Broken
Needs
Replaced
Replace



Door nsr
Dented
Over
30mm
Repair
and
Refinish



Door osr
Scratched
Over
25mm
Thru Paint
Refinish



Door osr
Scratched
Over
25mm
Thru Paint
Refinish



Bumper Rear Moulding
Scuffed
(Unpainted)
Over
100mm
Smart
Repair



Lamp osr
Broken
Needs
Replaced
Replace



Qtr Panel osr
Dented
Over
30mm
Repair
and
Refinish



Qtr Panel osr
Chipped
Multiple
Chips
Refinish



Qtr Panel osr
Scratched
Over
25mm
Thru Paint
Refinish



Door osf
Chipped
Multiple
Chips
Refinish



Bumper Front
Scratched
Over
100mm
Thru Paint
Refinish



Seat Base Cover osf
Torn
Over 3mm
Replace



Seat Base Cover nsf
Soiled
Heavy



Fascia Panel
Scuffed
Over
25mm
Smart

Replace

Repair

Comments

does not turn over.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.