



Carr Hill Industrial Estate
Doncaster
South Yorkshire
DN4 8DE
Tel: 01302 732600
Email: enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.

YH68MMF

CN: VF7YD2MFC12J80310

Photos



General Details

CITROEN RELAY 35 2.0 BLUEHDI ENTERPRISE 130PS

Vat Status: Commercial (plus Vat)

Mileage	84,377 miles	Miles Warranty	
Colour	Silver	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	17/01/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		17/01/2019	Yes



No V5

Extras

Stereo:	CD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	Yes
		Paint:	

Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm



Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Poor
Comments	

Service History

Service History	No
Stamps	

Photos



Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish

Door osr	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
C Post os	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Roof	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door Qtr Light osf	Cracked	Replace	Replace
Door Mirror Assy osf	Broken	Replace	Replace
Door Moulding osf	Broken	Replace	Replace
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door Pad osf	Soiled	Heavy	Replace
Carpets Front	Torn	Over 10mm	Replace
Fascia Panel	Broken	Replace	Replace
Seat Base Cover osf	Soiled	Heavy	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace
Seat Base Cover nsr	Soiled	Heavy	Replace
Seat Base Cover osr	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

K
Crack/Torn

Damage Assessment

Bonnet

Chipped

Multiple Chips

Refinish

Bumper Front

Scratched

Over 100mm Thru Paint

Refinish

Door Mirror Assy nsf

Broken

Needs Replaced

Replace

Door nsr

Dented

Over 30mm

Repair and Refinish

Door osr

Dented

Over 30mm

Repair and Refinish

Door osr

Scratched

Over 25mm Thru Paint

Refinish

Door osr

Scratched

Over 25mm Thru Paint

Refinish

C Post os

Scratched

Over 25mm Thru Paint

Refinish

Qtr Panel osr

Scratched

Over 25mm Thru Paint

Refinish



Dented
Over
30mm
Repair
and
Refinish



Dented
Over
30mm
Repair
and
Refinish



Scratched
Over
25mm
Thru Paint
Refinish



Roof
Scratched
Over
25mm
Thru Paint
Refinish



**Qtr Panel
osr**
Scratched
Over
25mm
Thru Paint
Refinish



**Door Qtr
Light osf**
Cracked
Needs
Replaced
Replace



**Door
Mirror
Assy osf**
Broken
Needs
Replaced
Replace



**Door
Moulding
osf**
Broken
Needs
Replaced
Replace



**Bumper
Front**
Scratched
Over
100mm
Thru Paint
Refinish




**Door Pad
osf**
Soiled
Heavy
Replace



**Carpets
Front**
Torn
Over
10mm
Replace



**Fascia
Panel**
Broken
Needs
Replaced
Replace



**Seat
Base
Cover
osf**
Soiled
Heavy
Replace



**Seat
Base
Cover
nsf**
Soiled
Heavy
Replace



**Seat
Base
Cover
nsr**
Soiled
Heavy
Replace



**Seat
Base
Cover
osr**
Soiled
Heavy
Replace

Comments

ign barrel fault

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.