



Commercial Vehicle Auctions Ltd.

MX19DYT

CN: VF1VA000862689557

Photos



General Details

RENAULT MASTER LL35 2.3 DCI BUSINESS

Vat Status: Commercial (plus Vat)

Mileage	134,747 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	01/08/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2019	Yes



Valid MOT
Expires: 08/08/2025



V5 with CVA

Extras

Stereo:	HDD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	Yes	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels


Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Dented	Over 30mm	Repair and Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Seat Base Cover osf	Holed	Over 3mm	Replace
Screen Front	Cracked	Replace	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat



Splat Key

S3
Scratch/Paint defect 100m +
D3
Dent/damage 100mm +
K
Crack/Torn

Damage Assessment



Bonnet
Dented
Over 30mm
Repair and Refinish




Wing nsf
Dented
Over 30mm
Repair and Refinish



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish




Qtr Panel nsr



Qtr Panel nsr



Qtr Panel osr

	Scratched Over 25mm Thru Paint Refinish		Scratched Over 25mm Thru Paint Refinish		Scratched Over 25mm Thru Paint Refinish
	Qtr Panel osr Scratched Over 25mm Thru Paint Refinish		Qtr Panel osr Dented Over 30mm Repair and Refinish		Door osf Dented Over 30mm Repair and Refinish
	Seat Base Cover osf Holed Over 3mm Replace		Screen Front Cracked Needs Replaced Replace		Seat Base Cover nsf Soiled Heavy Replace

Comments	
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.	

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.