



Commercial Vehicle Auctions Ltd.

N24ORR

CN: WF0YXXTTGYJT75168

Photos



General Details

FORD TRANSIT CUSTOM 300 BASE 2.0 TDCI 105PS

Vat Status: Commercial (plus Vat)

Mileage	98,583 miles	Miles Warranty	No
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Red
Reg Date	19/12/2018	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
	19/12/2018	2018	Yes



Valid MOT
Expires: 10/09/2025



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels


Alloy	OSF	3mm-5mm
Steel ✓	Depth	mm
	NSF	3mm-5mm
	Depth	mm
	OSR	3mm-5mm
	Depth	mm
	NSR	3mm-5mm
	Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Average
Comments	

Service History

Service History	No
Stamps	



Damage Lines

Component	Condition	Severity	Repair
General Interior	Soiled	Light	Clean
Bonnet	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Tailgate	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Sill ns	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Roof	Rusted	Over 5mm	Refinish



D2
Dent/damage 30-100mm
X
Req Replacement
V
Soiled/Valet
R
Rust

A photograph showing the interior of a vehicle, specifically the front seats and floor area. The seats are upholstered in a light-colored material, possibly leather or vinyl, and show significant wear, including scuffing and discoloration. The floor is covered in a dark, textured material, likely carpet or rubber matting, and appears dirty and worn. A black bag or bag is visible on the right seat. The overall condition suggests a vehicle that has been used extensively and may require maintenance or repair.

Soiled
Light
Clean



Dented
Over
30mm
Repair
and
Refinish



Dented
Between
10mm +
30mm
Smart
Repair



Dented
Over
30mm
Repair
and
Refinish



Dented
Over
30mm
Repair
and
Refinish



Dented
Over
30mm
Repair
and
Refinish



Broken
Needs
Replaced
Replace



Rusted
Over 5mm
Refinish

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.