



Commercial Vehicle Auctions Ltd.

DL70MGO

CN: VXEVFAHKKM7803927

Photos



General Details

VAUXHALL VIVARO 3100 2.0 DYNAMIC 120PS

Vat Status: Commercial (plus Vat)

Mileage	56,322 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	10/12/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
			Yes



Valid MOT
Expires: 11/03/2026



No V5

Extras

Stereo:	HDD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	Yes	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels





Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Panel Front	Chipped	Multiple Chips	Refinish
Qtr Panel Moulding ns	Missing	Replace	Replace
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Door Moulding nsr	Broken	Replace	Replace
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Wing osf	Scratched	Over 25mm Thru Paint	Refinish
Seat Base Cover osf	Torn	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat



Splat Key

S3
Scratch/Paint defect 100m +
D3
Dent/damage 100mm +
C2
Multiple Chips
K
Crack/Torn
M
Missing

Damage Assessment



Bonnet
Chipped
Multiple Chips
Refinish



Panel Front
Chipped
Multiple Chips
Refinish



Qtr Panel Mouldings
Missing
Needs Replaced
Replace



Qtr Panel nsr
Dented
Over 30mm
Repair and Refinish



Door nsr
Dented
Over 30mm
Repair and Refinish




Bumper Rear
Scratched
Over 100mm Thru Paint
Refinish




Door Moulding nsr
Broken
Needs Replaced
Replace



Door nsr
Dented
Over 30mm
Repair and Refinish



Door osr
Dented
Over 30mm
Repair and Refinish



Door osr
Dented
Over 30mm
Repair and Refinish




Door osr
Dented
Over 30mm
Repair and Refinish




Door osf
Dented
Over 30mm
Repair and Refinish



Wing osf
Scratched
Over 25mm Thru Paint
Refinish



Seat Base Cover osf
Torn
Over 3mm
Replace



Seat Base Cover nsf
Soiled
Heavy
Replace

Comments

clutch slipping.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.