



Commercial Vehicle Auctions Ltd.

NX66BYH

CN: VF3YC2MHU12C62283

Photos



General Details

PEUGEOT BOXER 335 2.0 BLUEHDI 130PS

Vat Status: Commercial (plus Vat)

Mileage	95,652 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	14/12/2016	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	14/12/2016 YOM	2016 Runner? Yes/No Yes



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Average
Comments	

Service History

Service History	No
Stamps	





Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Wing nsf	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door Moulding nsf	Missing	Replace	Replace
Door nsr	Rusted	Over 5mm	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door Pad osf	Soiled	Heavy	Replace
Carpets Front	Holed	Over 3mm	Replace
Seat Base Cover osf	Soiled	Heavy	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace
Door Pad nsf	Soiled	Heavy	Replace
Seat Base Cover nsr	Soiled	Heavy	Replace
Seat Base Cover osr	Soiled	Heavy	Replace

A top-down line drawing of a car chassis. The front of the car is on the right, and the rear is on the left. The front end features a grille with four vertical bars and four circular headlights. The rear end has a single circular taillight. The car has four wheels. Various components are labeled with red text: 'R' is located in the center of the rear floor; 'M' is located on the right side of the rear floor; 'S3' is located on the left side of the rear floor, near the rear wheel; 'S3' is located on the left side of the rear floor, near the rear wheel; 'S3' is located on the left side of the rear floor, near the rear wheel; 'C2' is located on the right side of the front floor, near the front wheel; 'C2' is located on the right side of the front floor, near the front wheel; 'S3' is located on the right side of the front floor, near the front wheel.

S3
Scratch/Paint defect 100m +
C2
Multiple Chips
M
Missing
R
Rust

Chipped
Multiple
Chips
Refinish



Chipped
Multiple
Chips
Refinish



Scratched
Over
100mm
Thru Paint
Refinish



Door



Door nsr



Qtr Panel



Moulding
nsf
Missing
Needs
Replaced
Replace



Rusted
Over 5mm
Refinish



nsr
Scratched
Over
25mm
Thru Paint
Refinish




Qtr Panel
osr
Scratched
Over
25mm
Thru Paint
Refinish



Door Pad
osf
Soiled
Heavy
Replace



Carpets
Front
Holed
Over 3mm
Replace



Seat
Base
Cover
osf
Soiled
Heavy
Replace



Seat
Base
Cover
nsf
Soiled
Heavy
Replace



Door Pad
nsf
Soiled
Heavy
Replace



Seat
Base
Cover
nsr
Soiled
Heavy
Replace



Seat
Base
Cover
osr
Soiled
Heavy
Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.