



## Commercial Vehicle Auctions Ltd.

**NX66SZV**

CN: VF37FBHY6GJ801388

### Photos



### General Details

PEUGEOT PARTNER 750 SE 1.6 BLUEHDI 100PS  
Vat Status: Commercial (plus Vat)

|              |              |                |        |
|--------------|--------------|----------------|--------|
| Mileage      | 60,720 miles | Miles Warranty |        |
| Colour       | White        | Fuel           | Diesel |
| Transmission | Manual       | Fuel Level     |        |
| Reg Date     | 10/11/2016   | Engine Size    |        |
| Body Type    |              |                |        |

### Details

|             |            |                |                |
|-------------|------------|----------------|----------------|
| Engine No   | Cab Type   | Plated Weight  | Doors          |
| Body Length | Axle Combi | Steering Combi | Rear Susp      |
| Gears       | 5 DFR      | YOM            | Runner? Yes/No |
|             |            | 2016           | Yes            |



**MOT Cert Here**  
**Expires: 08/10/2025**



**V5 with CVA**

### Extras

|                |       |                  |     |
|----------------|-------|------------------|-----|
| Stereo:        | CD    | Electric         | 2   |
| Interior:      | Cloth | Windows:         |     |
| Sat Nav:       | No    | Central Locking: | Yes |
| Air            | No    | Phone Kit:       | No  |
| Conditioning:  |       | Metallic Paint:  | No  |
| Cruise Control | No    |                  |     |

### Tyres & Wheels

|         |           |    |
|---------|-----------|----|
| Alloy   | OSF Depth | mm |
| Steel ✓ | NSF Depth | mm |
|         | OSR Depth | mm |
|         | NSR Depth | mm |



### Interior Condition

|            |         |
|------------|---------|
| Carpets    | Good    |
| Upholstery | Poor    |
| Seats      | Poor    |
| Odour      | Average |
| Comments   |         |

### Service History

|                 |    |
|-----------------|----|
| Service History | No |
| Stamps          |    |

## Photos



## Damage Lines

| Component     | Condition | Severity             | Repair              |
|---------------|-----------|----------------------|---------------------|
| Bonnet        | Chipped   | Multiple Chips       | Refinish            |
| Door nsr      | Chipped   | Multiple Chips       | Refinish            |
| Door osr      | Dented    | Over 30mm            | Repair and Refinish |
| Qtr Panel osr | Chipped   | Multiple Chips       | Refinish            |
| Qtr Panel osr | Scratched | Over 25mm Thru Paint | Refinish            |

|                     |        |       |         |
|---------------------|--------|-------|---------|
| Seat Base Cover osf | Soiled | Heavy | Replace |
| Seat Base Cover nsf | Soiled | Heavy | Replace |

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

| Damage Assessment                                                                  |                                                                                  |                                                                                     |                                                                                             |                                                                                       |                                                                                    |
|------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
|   | <b>Bonnet</b><br><br>Chipped<br><br>Multiple<br>Chips<br><br>Refinish            |   | <b>Door nsr</b><br><br>Chipped<br><br>Multiple<br>Chips<br><br>Refinish                     |   | <b>Door osr</b><br><br>Dented<br><br>Over<br>30mm<br><br>Repair<br>and<br>Refinish |
|  | <b>Qtr Panel<br/>osr</b><br><br>Chipped<br><br>Multiple<br>Chips<br><br>Refinish |  | <b>Qtr Panel<br/>osr</b><br><br>Scratched<br><br>Over<br>25mm<br>Thru Paint<br><br>Refinish |  | <b>Seat<br/>Base<br/>Cover<br/>osf</b><br><br>Soiled<br><br>Heavy<br><br>Replace   |
|  | <b>Seat<br/>Base<br/>Cover<br/>nsf</b><br><br>Soiled<br><br>Heavy<br><br>Replace |                                                                                     |                                                                                             |                                                                                       |                                                                                    |

| Comments                                                                                                                                        |
|-------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p> |

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.