



Carr Hill Industrial Estate  
Doncaster  
South Yorkshire  
DN4 8DE  
Tel: 01302 732600  
Email: enquiries@cva-auctions.co.uk

# Commercial Vehicle Auctions Ltd.

FJ14DBV

CN: ZFA25000002514393

## Photos



## General Details

FIAT DUCATO 35 MAXI 2.3 MULTIJET

Vat Status: Commercial (plus Vat)

|              |              |                |        |
|--------------|--------------|----------------|--------|
| Mileage      | 58,116 miles | Miles Warranty |        |
| Colour       | Red          | Fuel           | Diesel |
| Transmission | Auto         | Fuel Level     |        |
| Reg Date     | 20/03/2014   | Engine Size    |        |
| Body Type    |              |                |        |

## Details

|             |            |                |                |
|-------------|------------|----------------|----------------|
| Engine No   | Cab Type   | Plated Weight  | Doors          |
| Body Length | Axle Combi | Steering Combi | Rear Susp      |
| Gears       | DFR        | YOM            | Runner? Yes/No |
|             | 20/03/2014 | 2014           | Yes            |



Valid MOT  
Expires: 12/12/2025



No V5

## Extras

|                |       |                  |     |
|----------------|-------|------------------|-----|
| Stereo:        | CD    | Electric         | 2   |
| Interior:      | Cloth | Windows:         |     |
| Sat Nav:       | No    | Central Locking: | Yes |
| Air            | No    | Phone Kit:       | No  |
| Conditioning:  |       | Metallic Paint:  | No  |
| Cruise Control | No    |                  |     |

## Tyres & Wheels

|         |           |    |
|---------|-----------|----|
| Alloy   | OSF Depth | mm |
| Steel ✓ | NSF Depth | mm |
|         | OSR Depth | mm |
|         | NSR Depth | mm |

## Interior Condition

|            |      |
|------------|------|
| Carpets    | Good |
| Upholstery | Poor |
| Seats      | Poor |
| Odour      | Good |
| Comments   |      |

## Service History

|                 |    |
|-----------------|----|
| Service History | No |
| Stamps          |    |



Damage Lines

| Component                    | Condition           | Severity              | Repair       |
|------------------------------|---------------------|-----------------------|--------------|
| Bonnet                       | Chipped             | Multiple Chips        | Refinish     |
| Number Plate Front           | Broken              | Replace               | Replace      |
| Bumper Front                 | Scratched           | Over 100mm Thru Paint | Refinish     |
| Door nsf                     | Chipped             | Multiple Chips        | Refinish     |
| Wing Front Arch Extension os | Scuffed (Unpainted) | Over 100mm            | Smart Repair |

|                     |        |       |         |
|---------------------|--------|-------|---------|
| Door Pad osf        | Soiled | Heavy | Replace |
| Seat Base Cover osf | Soiled | Heavy | Replace |
| Seat Base Cover nsf | Soiled | Heavy | Replace |
| Door Pad nsf        | Soiled | Heavy | Replace |

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**C2**  
Multiple Chips

**K**  
Crack/Torn

Damage Assessment

|                                                                             |                                                                                                             |                                                                                          |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|
| <div> <b>Bonnet</b><br/> Chipped<br/> Multiple Chips<br/> Refinish </div>   | <div> <b>Number Plate Front</b><br/> Broken<br/> Needs Replaced<br/> Replace </div>                         | <div> <b>Bumper Front</b><br/> Scratched<br/> Over 100mm Thru Paint<br/> Refinish </div> |
| <div> <b>Door nsf</b><br/> Chipped<br/> Multiple Chips<br/> Refinish </div> | <div> <b>Wing Front Arch Extension os</b><br/> Scuffed (Unpainted)<br/> Over 100mm<br/> Smart Repair </div> | <div> <b>Door Pad osf</b><br/> Soiled<br/> Heavy<br/> Replace </div>                     |
| <div> <b>Seat Base Cover osf</b><br/> Soiled<br/> Heavy<br/> Replace </div> | <div> <b>Seat Base Cover nsf</b><br/> Soiled<br/> Heavy<br/> Replace </div>                                 | <div> <b>Door Pad nsf</b><br/> Soiled<br/> Heavy<br/> Replace </div>                     |

#### Comments

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.