




Commercial Vehicle Auctions Ltd.

YV68BVJ

CN: 6FPPXXMJ2PJR48105



General Details

FORD RANGER 2.2 TDCI
 Vat Status: Commercial (plus Vat)

Mileage	68,638 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	24/01/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	24/01/2019	Runner? Yes/No
		YOM	2019
			Yes

	Valid MOT Expires: 24/01/2026		No V5
--	---	---	--------------

Extras

Stereo:	Radio	Electric	4
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	No	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Poor
Seats	Poor
Odour	Good
Comments	

Service History


Service History	No
Stamps	



Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Door Mirror Assy nsf	Scuffed (Unpainted)	Over 100mm	Smart Repair
Tailgate	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Sill os	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Door Pad osr	Scuffed	Over 25mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door Pad nsf	Soiled	Heavy	Replace
Seat Base Cover osf	Soiled	Heavy	Replace


Vehicle Splat



Splat Key

- S2**
Scratch/Paint defect 30-100mm
- S3**
Scratch/Paint defect 100mm +
- D2**
Dent/damage 30-100mm
- D3**
Dent/damage 100mm +
- C2**
Multiple Chips

Damage Assessment



Bonnet

Chipped
Multiple Chips
Refinish



Bumper Front

Scratched
25 to 100mm Thru Paint
Smart Repair



Door Mirror Assy nsf

Scuffed (Unpainted)
Over 100mm
Smart Repair



Tailgate

Dented
Over 30mm
Repair and Refinish



Qtr Panel osr

Dented
Over 30mm
Repair and Refinish



Sill os

Dented
Over 30mm
Repair and Refinish



Door osf



Door Pad



Wing osf



Dented
Over
30mm
Repair
and
Refinish



osr
Scuffed
Over
25mm
Smart
Repair



Scratched
Over
25mm Not
Thru Paint
Machine
Polish



**Bumper
Front**
Scratched
Over
100mm
Thru Paint
Refinish



**Door Pad
nsf**
Soiled
Heavy
Replace



**Seat
Base
Cover
osf**
Soiled
Heavy
Replace

Comments

rear canopy

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.