



# Commercial Vehicle Auctions Ltd.

PO19ZZD

CN: WDB9076332P089390

## Photos



## General Details

MERCEDES-BENZ SPRINTER 316 CDI

Vat Status: Commercial (plus Vat)

|              |               |                |        |
|--------------|---------------|----------------|--------|
| Mileage      | 118,527 miles | Miles Warranty |        |
| Colour       | White         | Fuel           | Diesel |
| Transmission | Manual        | Fuel Level     |        |
| Reg Date     | 26/03/2019    | Engine Size    |        |
| Body Type    |               |                |        |

## Details

|             |            |                |                         |
|-------------|------------|----------------|-------------------------|
| Engine No   | Cab Type   | Plated Weight  | Doors                   |
| Body Length | Axle Combi | Steering Combi | Rear Susp               |
| Gears       | 6 DFR      | 26/03/2019 YOM | 2019 Runner? Yes/No Yes |



No V5

## Extras

|                |       |            |           |
|----------------|-------|------------|-----------|
| Stereo:        | Radio | Electric   | 2         |
| Interior:      | Cloth | Windows:   |           |
| Sat Nav:       | No    | Central    | Yes       |
| Air            | No    | Locking:   |           |
| Conditioning:  |       | Phone Kit: | BlueTooth |
| Cruise Control | Yes   | Metallic   | No        |
|                |       | Paint:     |           |

## Tyres & Wheels



|         |           |    |
|---------|-----------|----|
| Alloy   | OSF Depth | mm |
| Steel ✓ | NSF Depth | mm |
|         | OSR Depth | mm |
|         | NSR Depth | mm |

## Interior Condition

|            |      |
|------------|------|
| Carpets    | Good |
| Upholstery | Poor |
| Seats      | Poor |
| Odour      | Good |
| Comments   |      |


## Service History



|                 |    |
|-----------------|----|
| Service History | No |
| Stamps          |    |





| Damage Lines        |           |                |          |
|---------------------|-----------|----------------|----------|
| Component           | Condition | Severity       | Repair   |
| Bonnet              | Chipped   | Multiple Chips | Refinish |
| Roof                | Rusted    | Over 5mm       | Refinish |
| Door Moulding nsf   | Missing   | Replace        | Replace  |
| Door Moulding nsf   | Missing   | Replace        | Replace  |
| Door Moulding osf   | Missing   | Replace        | Replace  |
| Door Pad osf        | Soiled    | Heavy          | Replace  |
| Seat Base Cover osf | Torn      | Over 3mm       | Replace  |
| Seat Base Cover nsf | Soiled    | Heavy          | Replace  |
| Screen Front        | Scratched | Over 30mm      | Replace  |

| Vehicle Splat                                                                      | Splat Key                                                                                                                                 |
|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|
|  | <p><b>S3</b><br/>Scratch/Paint defect 100m +</p> <p><b>C2</b><br/>Multiple Chips</p> <p><b>M</b><br/>Missing</p> <p><b>R</b><br/>Rust</p> |

| Damage Assessment                                                                  |                                                                                     |                                                                                     |                                                                                     |                                                                                       |                                                                                     |
|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  | <p><b>Bonnet</b></p> <p>Chipped</p> <p>Multiple Chips</p> <p>Refinish</p>           |  | <p><b>Roof</b></p> <p>Rusted</p> <p>Over 5mm</p> <p>Refinish</p>                    |  | <p><b>Door Moulding nsf</b></p> <p>Missing</p> <p>Needs Replaced</p> <p>Replace</p> |
|  | <p><b>Door Moulding nsf</b></p> <p>Missing</p> <p>Needs Replaced</p> <p>Replace</p> |  | <p><b>Door Moulding osf</b></p> <p>Missing</p> <p>Needs Replaced</p> <p>Replace</p> |  | <p><b>Door Pad osf</b></p> <p>Soiled</p> <p>Heavy</p> <p>Replace</p>                |
|  | <p><b>Seat Base Cover osf</b></p> <p>Torn</p> <p>Over 3mm</p>                       |  | <p><b>Seat Base Cover nsf</b></p> <p>Soiled</p> <p>Heavy</p>                        |  | <p><b>Screen Front</b></p> <p>Scratched</p> <p>Over 30mm</p> <p>Replace</p>         |

 Replace Replace

#### Comments

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.