



Commercial Vehicle Auctions Ltd.

YB12DAO

CN: AHTFR22G106055594

Photos



General Details

TOYOTA HILUX 2.5 D-4D 144PS

Vat Status: Commercial (plus Vat)

Mileage	110,793 miles	Miles Warranty	
Colour	Silver	Fuel	Diesel
Transmission	Manual	Fuel Level	
Reg Date	29/06/2012	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	5 DFR	29/06/2012	Runner? Yes/No
		YOM	Yes



Valid MOT
Expires: 29/06/2025



No V5

Extras

Stereo:	CD	Electric	4
Interior:	Cloth	Windows:	
Sat Nav:	No	Central Locking:	Yes
Air	Yes	Phone Kit:	No
Conditioning:		Metallic Paint:	Yes
Cruise Control	No		

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm



Interior Condition

Carpets	Poor
Upholstery	Poor
Seats	Poor
Odour	Average
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Door nsr	Dented	Over 30% Of Panel	Replace
C Post ns	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Rusted	Over 5mm	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Rusted	Over 5mm	Refinish
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Dented	Over 30mm	Repair and Refinish
Door Pad osf	Soiled	Heavy	Replace
Seat Base Cover osf	Torn	Over 3mm	Replace
Carpets Front	Holed	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3
 Scratch/Paint defect 100m +
D3
 Dent/damage 100mm +
C2
 Multiple Chips
R
 Rust



Damage Assessment



Bonnet

Chipped
Multiple
Chips
Refinish




Door nsr

Dented
Over 30%
Of Panel
Replace



C Post ns

Dented
Over
30mm
Repair
and
Refinish



Qtr Panel nsr

Dented
Over
30mm
Repair
and
Refinish



Qtr Panel nsr

Rusted
Over 5mm
Refinish



Qtr Panel nsr

Dented
Over
30mm
Repair
and
Refinish



Qtr Panel osr

Scratched
Over
25mm
Thru Paint
Refinish



Qtr Panel osr

Rusted
Over 5mm
Refinish




Door osf

Scratched
Over
25mm
Thru Paint
Refinish




Bumper Front

Dented
Over
30mm
Repair
and
Refinish



Door Pad osf

Soiled
Heavy
Replace



Seat Base Cover osf

Torn
Over 3mm
Replace



Carpets Front

Holed
Over 3mm



Seat Base Cover nsf

Soiled



Replace



Heavy

Replace

Comments

rear canopy

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.