

Carr Hil Industrial Estate Doncaster South Yorkshire DN4 8DE Tel: 01302 732600 Email: enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.



CN: WF0XXXTTGXHE68292

Photos



General Details

FORD TRANSIT 350 2.0 TDCI 130PS Vat Status: Commercial (plus Vat)

- Mileage113,983 milesColourWhiteTransmissionManualReg Date01/03/2018Body TypeVertical
- Miles Warranty Fuel Fuel Level Engine Size

Diesel

Engine No	Cab Type		Plated Weight		Doors		
Body Length	Axle Combi		Steering Combi		Rear Susp		
Gears	6 DFR	01/03/2018	YOM	2018	Runner? Yes/No	Yes	



Details

Valid MOT Expires: 28/02/2026



No V5

ixtras				Tyres & Wheels			Interior Condition		Service History	
Stereo: Interior: Sat Nav: Air Conditioning: Cruise Control	Radio Cloth No No	Electric Windows: Central Locking: Phone Kit: Metallic Paint:	2 Yes BlueTooth No	Alloy Steel √	OSF Depth NSF Depth OSR Depth NSR Depth	3mm-5mm mm 3mm-5mm mm 2mm mm 3mm-5mm mm	Carpets Upholster Seats Odour Comment	Average ry Average Average Average s	Service History Stamps	No






























Damage Lines

- Component Sill os Seat Base Cover osf Roof Bonnet Bumper Front Moulding Wing osf Wing Front Arch Extension os Door osf Qtr Panel osr Tailgate Bumper Rear Moulding Qtr Panel nsr
- Condition Scratched Torn Rusted Chipped Scuffed (Unpainted) Dented Dented Dented Rusted Scuffed (Unpainted) Dented

Severity Over 25mm Thru Paint Over 3mm Over 5mm 1 To 5 Over 100mm With Paint Damage With Paint Damage With Paint Damage Over 5mm Over 100mm With Paint Damage

Repair Refinish Replace Refinish Smart Repair Smart Repair Repair and Refinish Replace Repair and Refinish Repair and Refinish Refinish Smart Repair Scuffed (Unpainted) Dented

Over 100mm With Paint Damage Smart Repair Repair and Refinish




Damage Assessment



Sill os Scratched

> Over 25mm Thru Paint Refinish



TRANSIT











Seat Base Cover osf

Torn

Over 3mm

Replace

Bumper Front Moulding

(Unpainted) Over

Scuffed

Dented With Paint Damage

Repair and Refinish

Bumper Rear Moulding Scuffed (Unpainted)



Roof Rusted Over 5mm Refinish



Qtr Panel osr Dented With Paint Damage Repair and Refinish

Qtr Panel nsr Dented With Paint




Replaced

Tailgate Rusted Over 5mm Refinish











Over 100mm Smart Repair



Damage Repair

and Refinish



Qtr Panel Moulding ns

Scuffed (Unpainted) Over

Smart Repair

100mm



Door nsr

Dented With Paint Damage Repair

and Refinish

Comments

ADD BLUE WARNING LIGHT

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.