



Commercial Vehicle Auctions Ltd.

FJ19GOH

CN: VF1MA000761880078

Photos



General Details

RENAULT MASTER MM35 BUSINESS 2.3 DCI
130PS

Vat Status: Commercial (plus Vat)

Mileage	115,820 miles	Miles Warranty	Yes
Colour	White	Fuel	Diesel
Transmission	Manual	Fuel Level	Quarter
Reg Date	06/03/2019	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	6 DFR	YOM	Runner? Yes/No
		2019	No



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone	No
Cruise Control	No	Kit:	
		Metallic	No
		Paint:	
		Other:	Vehicle will not power up

Tyres & Wheels




Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets
Upholstery
Seats
Odour
Comments

Service History

Service	No
History	
Stamps	



Damage Lines

Component	Condition	Severity	Repair
Seat Back Cover osf	Torn	Over 3mm	Replace
Door Moulding osf	Broken	Replace	Replace
Door Mirror Assy osf	Broken	Replace	Replace
Bumper Front	Insecure	Action Required	Smart Repair
Bonnet	Dented	2 Or Less UpTo 10mm	Smart Repair

Bonnet	Dented	2 Or Less UpTo 10mm	Smart Repair
Wing nsf	Scratched	UpTo 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Cracked	Replace	Replace
Sill ns	Cracked	Replace	Replace
Sill ns	Rusted	Over 5mm	Refinish
Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Tailgate Trim Panel	Missing	Replace	Replace
Qtr Panel Trim os	Missing	Replace	Replace

Damage Assessment					
	Seat Back Cover osf Torn Over 3mm Replace		Door Moulding osf Broken Needs Replaced Replace		Door Mirror Assy osf Broken Needs Replaced Replace
	Bumper Front Insecure Action Required Smart Repair		Bonnet Dented 2 Or Less UpTo 10mm Smart Repair		Bonnet Dented 2 Or Less UpTo 10mm Smart Repair
	Wing nsf Scratched UpTo 25mm Not Thru Paint Machine Polish		Bumper Front Scratched Over 25mm Not Thru Paint Machine Polish		Qtr Panel nsr Cracked Needs Replaced Replace
	Sill ns Cracked Needs Replaced Replace		Sill ns Rusted Over 5mm Refinish		Qtr Panel nsr Dented Between 10mm + 30mm Smart Repair
	Door osr Dented 2 Or Less UpTo 10mm Smart Repair		Door nsr Dented 2 Or Less UpTo 10mm Smart Repair		Tailgate Trim Panel Missing Needs Replaced Replace



Qtr Panel
Trim os
Missing
Needs
Replaced
Replace

Comments
Vehicle will not power up cranks but will not fire No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.