



Commercial Vehicle Auctions Ltd.

PJ20GXG

CN: W1V9076352P249668

Photos



General Details

MERCEDES-BENZ SPRINTER 314 CDI

Vat Status: Commercial (plus Vat)

Mileage	223,140 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	15/07/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	15/07/2020	2020	Yes



Valid MOT
Expires: 19/07/2025



V5 with CVA

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service History	No
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Roof	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Badgedecal Rear	Missing	Replace	Replace
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Cracked	Replace	Replace
Qtr Panel Moulding os	Scuffed (Unpainted)	Over 100mm	Smart Repair
Screen Front	Chipped	Over 10mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat



Splat Key

- S3**
Scratch/Paint defect 100m +
- D3**
Dent/damage 100mm +
- C1**
Single Chip
- C2**
Multiple Chips
- M**
Missing

Damage Assessment



Bonnet

- Chipped
- Multiple Chips
- Refinish



Bumper Front

- Scratched
- Over 100mm Thru Paint
- Refinish



Door nsf

- Dented
- Over 30mm
- Repair and Refinish



Roof

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
nsr**

Dented

Over
30mm

Repair
and
Refinish



**Badgedecal
Rear**

Missing

Needs
Replaced

Replace



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Dented

Over
30mm

Repair
and
Refinish



**Qtr Panel
osr**

Cracked

Needs
Replaced

Replace



**Qtr Panel
Moulding
os**

Scuffed
(Unpainted)

Over
100mm

Smart
Repair



**Screen
Front**

Chipped

Over
10mm

Replace



**Seat
Base
Cover
nsf**

Soiled

Heavy

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.