



Commercial Vehicle Auctions Ltd.

PJ20KBK

CN: W1V9076352P251985

Photos



General Details

MERCEDES-BENZ SPRINTER 314 CDI

Vat Status: Commercial (plus Vat)

Mileage	193,661 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	15/07/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	15/07/2020	2020	Yes



Valid MOT
Expires: 06/06/2025



No V5

Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Poor
Upholstery	Average
Seats	Poor
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	



Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel Moulding ns	Scuffed (Unpainted)	Over 100mm	Smart Repair
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
C Post ns	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Badgedecal Rear	Broken	Replace	Replace
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Carpets Front	Holed	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3

Scratch/Paint defect 100m +

D3

Dent/damage 100mm +

C2

Multiple Chips

K

Crack/Torn

Damage Assessment					
	Bonnet		Wing nsf		Door nsf
	Chipped		Dented		Dented
	Multiple Chips		Over 30mm		Over 30mm
	Refinish		Repair and Refinish		Repair and Refinish
	Door nsf		Qtr Panel nsr		Qtr Panel Moulding ns
	Dented		Dented		Scuffed
	Over				



30mm
Repair
and
Refinish



Over
30mm
Repair
and
Refinish



(Unpainted)
Over
100mm
Smart
Repair



**Qtr Panel
nsr**
Dented
Over
30mm
Repair
and
Refinish



**Qtr Panel
nsr**
Dented
Over
30mm
Repair
and
Refinish



Door nsr
Dented
Over
30mm
Repair
and
Refinish



C Post ns
Dented
Over
30mm
Repair
and
Refinish



Door osr
Dented
Over
30mm
Repair
and
Refinish



**Badgedecal
Rear**
Broken
Needs
Replaced
Replace



Door osr
Dented
Over
30mm
Repair
and
Refinish



**Qtr Panel
osr**
Scratched
Over
25mm
Thru Paint
Refinish



**Qtr Panel
osr**
Dented
Over
30mm
Repair
and
Refinish



**Qtr Panel
osr**
Scratched
Over
25mm
Thru Paint
Refinish



**Qtr Panel
osr**
Dented
Over
30mm
Repair
and
Refinish



Door osf
Dented
Over
30mm
Repair
and
Refinish



**Carpets
Front**
Holed
Over 3mm
Replace



**Seat
Base
Cover
nsf**
Soiled
Heavy
Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.