



# Commercial Vehicle Auctions Ltd.

PJ20KXM

CN: W1V9076352P253652

## Photos



## General Details

MERCEDES-BENZ SPRINTER 314 CDI

Vat Status: Commercial (plus Vat)

Mileage	191,319 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	17/07/2020	Engine Size	
Body Type			

## Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	17/07/2020	2020	Yes



Valid MOT  
Expires: 23/07/2025



V5 with CVA

## Extras

Stereo:	Radio	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

## Tyres & Wheels

Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

## Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

## Service History

Service	No
History	
Stamps	



## Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish



Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Badgedecal Rear	Missing	Replace	Replace
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Wing osf	Dented	Over 30mm	Repair and Refinish
Door Moulding osf	Missing	Replace	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

### Vehicle Splat

### Splat Key

**S3**  
Scratch/Paint defect 100m +

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

**M**  
Missing

Damage Assessment					
	<b>Bonnet</b>  Chipped  Multiple Chips  Refinish		<b>Bumper Front</b>  Scratched  Over 100mm Thru Paint  Refinish		<b>Wing nsf</b>  Scratched  Over 25mm Not Thru Paint  Machine Polish
	<b>Qtr Panel nsr</b>  Dented  Over 30mm  Repair and Refinish		<b>Qtr Panel nsr</b>  Dented  Over 30mm  Repair and Refinish		<b>Qtr Panel nsr</b>  Scratched  Over 25mm Thru Paint  Refinish
	<b>Qtr Panel nsr</b>  Scratched  Over 25mm Thru Paint  Refinish		<b>Door nsr</b>  Dented  Over 30mm  Repair and Refinish		<b>Door osr</b>  Dented  Over 30mm  Repair and Refinish



**Badgedecal  
Rear**

Missing

Needs  
Replaced

Replace



**Qtr Panel  
osr**

Dented

Over  
30mm

Repair  
and  
Refinish



**Wing osf**

Dented

Over  
30mm

Repair  
and  
Refinish



**Door  
Moulding  
osf**

Missing

Needs  
Replaced

Replace



**Seat  
Base  
Cover  
nsf**

Soiled

Heavy

Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.