



Carr Hill Industrial Estate
Doncaster
South Yorkshire
DN4 8DE
Tel: 01302 732600
Email: enquiries@cva-auctions.co.uk

Commercial Vehicle Auctions Ltd.

PK20UXU

CN: W1V9076352P248596

Photos



General Details

MERCEDES-BENZ SPRINTER 314 CDI

Vat Status: Commercial (plus Vat)

Mileage	211,931 miles	Miles Warranty	
Colour	White	Fuel	Diesel
Transmission	Auto	Fuel Level	
Reg Date	14/07/2020	Engine Size	
Body Type			

Details

Engine No	Cab Type	Plated Weight	Doors
Body Length	Axle Combi	Steering Combi	Rear Susp
Gears	DFR	YOM	Runner? Yes/No
	14/07/2020	2020	Yes



Valid MOT
Expires: 15/07/2025



V5 with CVA

Extras

Stereo:	HDD	Electric	2
Interior:	Cloth	Windows:	
Sat Nav:	No	Central	Yes
Air	No	Locking:	
Conditioning:		Phone Kit:	BlueTooth
Cruise Control	Yes	Metallic	No
		Paint:	

Tyres & Wheels



Alloy	OSF Depth	mm
Steel ✓	NSF Depth	mm
	OSR Depth	mm
	NSR Depth	mm

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Poor
Odour	Good
Comments	

Service History

Service	No
History	
Stamps	






Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Badgedecal Rear	Missing	Replace	Replace
Bumper Rear Moulding	Missing	Replace	Replace
Qtr Panel Moulding os	Scuffed (Unpainted)	Over 100mm	Smart Repair
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Seat Base Cover osf	Holed	Over 3mm	Replace
Seat Base Cover nsf	Soiled	Heavy	Replace

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +
D3
Dent/damage 100mm +
C2
Multiple Chips
M
Missing



Damage Assessment



Bonnet

Chipped
Multiple
Chips
Refinish



Qtr Panel nsr

Dented
Over
30mm
Repair
and
Refinish



Qtr Panel nsr

Scratched
Over
25mm
Thru Paint
Refinish



Door nsr

Dented
Over
30mm
Repair
and
Refinish



Door osr

Dented
Over
30mm
Repair
and
Refinish



Badgedecal Rear

Missing
Needs
Replaced
Replace



Bumper Rear Moulding

Missing
Needs
Replaced
Replace



Qtr Panel Moulding os

Scuffed
(Unpainted)
Over
100mm
Smart
Repair



Qtr Panel osr

Dented
Over
30mm
Repair
and
Refinish




Door osf

Dented
Over
30mm
Repair
and
Refinish



Seat Base Cover osf

Holed
Over 3mm
Replace



Seat Base Cover nsf

Soiled
Heavy
Replace

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.