



## Commercial Vehicle Auctions Ltd.

**FN69AYB**

CN: XLRAEL1500L489931

### Photos



### General Details

DAF LF 180 EURO 6 7.5 TONNE

Vat Status: Commercial (plus Vat)

|              |            |                |        |
|--------------|------------|----------------|--------|
| Mileage      | 133,947 km | Miles Warranty |        |
| Colour       | White      | Fuel           | Diesel |
| Transmission | Manual     | Fuel Level     |        |
| Reg Date     | 04/10/2019 | Engine Size    |        |
| Body Type    |            |                |        |

### Details

|             |            |            |                |           |                |
|-------------|------------|------------|----------------|-----------|----------------|
| Engine No   | Cab Type   | Crew Cab   | Plated Weight  | Doors     |                |
| Body Length | Axle Combi | 4x2        | Steering Combi | Rear Susp | Spring         |
| Gears       | 6 DFR      | 04/10/2019 | YOM            | 2019      | Runner? Yes/No |
|             |            |            |                |           | Yes            |



**Valid MOT**  
**Expires: 31/12/2025**



**V5 with CVA**

### Extras






|                   |       |                   |     |
|-------------------|-------|-------------------|-----|
| Stereo:           | CD    | Electric Windows: | 2   |
| Interior:         | Cloth | Central Locking:  | Yes |
| Sat Nav:          | No    | Phone Kit:        | No  |
| Air Conditioning: | No    | Metallic Paint:   | No  |
| Cruise Control    | Yes   |                   |     |

### Interior Condition

|            |      |
|------------|------|
| Carpets    | Good |
| Upholstery | Good |
| Seats      | Poor |
| Odour      |      |
| Comments   |      |

### Service History

|                 |    |
|-----------------|----|
| Service History | No |
| Stamps          |    |



## Damage Lines

| Component             | Condition           | Severity             | Repair       |
|-----------------------|---------------------|----------------------|--------------|
| Bumper Front Moulding | Scuffed (Unpainted) | Over 100mm           | Smart Repair |
| Wing nsf              | Cracked             | Replace              | Replace      |
| Qtr Panel nsr         | Scratched           | Over 25mm Thru Paint | Refinish     |
| Qtr Panel osr         | Cracked             | Replace              | Replace      |
| Qtr Panel osr         | Cracked             | Replace              | Replace      |



|                     |           |                      |          |
|---------------------|-----------|----------------------|----------|
| Door osf            | Scratched | Over 25mm Thru Paint | Refinish |
| Seat Base Cover osf | Torn      | Over 3mm             | Replace  |

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**K**  
Crack/Torn

Damage Assessment

Bumper Front Moulding

Scuffed (Unpainted)  
Over 100mm  
Smart Repair

Wing nsf

Cracked  
Needs Replaced  
Replace

Qtr Panel nsr

Scratched  
Over 25mm Thru Paint  
Refinish

Qtr Panel osr

Cracked  
Needs Replaced  
Replace

Qtr Panel osr

Cracked  
Needs Replaced  
Replace

Door osf

Scratched  
Over 25mm Thru Paint  
Refinish

Seat Base Cover osf

Torn  
Over 3mm  
Replace

#### Comments

**No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.**

The details within this inspection report are correct at point of vehicle arrival. Updates, errors and omissions will be highlighted by the CVA Auctions via catalogues, the website, entry forms or by the auctioneer.