

VEHICLE INSPECTION REPORT

KU21ZFV

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	08/03/2021	VIN	WDB9071352N057760	CAP Below	£11,100.00
Year	2021	Body Style	Luton L3	Gearbox	MANUAL
Mileage	101,526 Miles Not Warranted	MOT Due	07/03/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£15,100.00		
Colour	WHITE	CAP Average	£13,500.00		

AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
Hole
Over 10mm

4: Other
N/A
N/A



5: Qtr Panel nsr
Hole
Over 10mm

6: Qtr Panel nsr
Hole
Over 10mm



7: Lamp nsr
Broken
Replace

8: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



9: Other
N/A
N/A

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	