

VEHICLE INSPECTION REPORT

BJ22KHY

Nissan Interstar TEKNA 2.3 DCI 135PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	31/03/2022	VIN	VNVM1000X68767213	CAP Average	£8,450.00
Year	2022	Body Style	Panel Van L3	CAP Below	£7,125.00
Mileage	88,622 Miles Not Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	30/03/2026	Gears	6
Colour	WHITE	CAP Clean	£9,325.00		

WARNING LIGHT ON DASH SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Other
N/A
N/A



5: Other
N/A
N/A

6: Door nsf
Dented
Over 2 UpTo 10mm



7: B Post ns
Scratched
UpTo 25mm Not Thru Paint

8: Sill ns
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Lamp osr
Broken
Replace



13: Lamp osr
Broken
Replace

14: Qtr Panel osr
Dented
Between 10mm + 30mm





15: Qtr Panel Moulding os
Missing
Replace

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Other
N/A
N/A

18: Qtr Panel osr
Dented
Over 30mm



19: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK