

VEHICLE INSPECTION REPORT

PO13DZL

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 03/04/2013

Year 2013

Mileage 1,020,720 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRAE45FF0L425132

Body Style Box Van

Service history Yes

Service documents Printout

MOT Due 31/05/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tail Lift Cantilever

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Roof
Dented
With Paint Damage

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Bumper Front
Dented
With Paint Damage



9: Door Mirror Glass os
Missing
Replace

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Pad osf
Soiled
Heavy

12: Fascia Panel
Soiled
Heavy



13: Seat Base Cover nsf
Burn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		