

VEHICLE INSPECTION REPORT

MJ67YMF

Daf CF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/01/2018

Year 2018

Mileage 573,992 Km Warranted

Fuel Type Diesel

Colour RED

VIN XLRAEM3700G164931

Body Style Flatbed

MOT Due 30/09/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Air



SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos








Condition Check





Damage Photos




1: Wing os
Scratched
Over 25mm Thru Paint


2: Fog Lamp Surround os
Broken
Replace



3: Bumper Front
Dented
With Paint Damage





4: Bonnet
Chipped
Multiple Chips




5: Screen Front
Chipped
Over 10mm


6: Bumper Front
Dented
With Paint Damage



7: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint





8: Wing nsf
Scratched
Over 25mm Thru Paint





9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Other
N/A
N/A





11: Door nsf
Scratched
Over 25mm Not Thru Paint

12: Other
N/A
N/A





13: Other
N/A
N/A

14: Bumper Rear
Rusted
Over 5mm





15: Other
N/A
N/A

16: Other
N/A
N/A




17: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm


18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Other
N/A
N/A



20: Other
N/A
N/A



21: Seat Base Cover osf
Torn
Over 3mm

22: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK