

VEHICLE INSPECTION REPORT

PE17HRM

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 15/03/2017

VIN XLRTGM4100G150030

Gearbox AUTOMATIC

Year 2017

Body Style Tractor Unit

Axle Combi 6x2

Mileage 870,562 Km Warranted

Service history Yes

Steering Combi Mid-Lift

Fuel Type Diesel

MOT Due 28/02/2026

Rear Suspension Air

Colour RED

Cab Type SLEEPER CAB

COLLECTED AS NON-RUNNER, GRILL, MATS & AIRBAGS REQUIRE ATTENTION SLIDING 5TH WHEEL, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3





OSO4


Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Dented
With Paint Damage

4: Wing nsf
Cracked
Replace



5: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

6: Qtr Panel Moulding os
Broken
Replace




7: Panel Rear
Dented
With Paint Damage

8: Door osf
Dented
With Paint Damage



9: Bumper Front
Dented
With Paint Damage

10: Screen Front
Chipped
UpTo 10mm



11: Door osf
Dented
Over 30mm

12: Carpets Front
Holed
Over 3mm



13: Switches And Controls
Missing
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		