

VEHICLE INSPECTION REPORT

PE63MYT

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/10/2013

VIN XLRAE45FF0L431773

Gearbox MANUAL

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 785,383 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 31/05/2026

Tail Lift Column

Colour RED

Cab Type DAY CAB

INTERMITTENT STARTER

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3






OSO4

Features


- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front
Cracked
Over 25mm

4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Qtr Panel osr
Cracked
Replace



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint

14: Door osf
Chipped
Edge Chip



15: Moulding of Wing
Broken
Replace

16: Door Mirror Assy of
Scratched (Painted)
Over 25mm Thru Paint




17: Carpets Front
Holed
Over 3mm

18: Seat Base Cover of
Holed
Over 3mm



19: Switches And Controls
Missing
Replace

20: Switches And Controls
Missing
Replace



21: Steering Wheel
 Damaged
 Replace

22: Other
 N/A
 N/A

Interior

Carpet Condition	Poor		Upholstery Condition	OK
Seat Condition	Poor		Odour	-
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			