

VEHICLE INSPECTION REPORT

PE17HSJ

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/03/2017

Year 2017

Mileage 1,126,039 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G150646

Body Style Tractor Unit

MOT Due 31/07/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

COLLECTED AS NON-RUNNER, REAR SPRING NEEDS ATTN



Tyres









NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips

2: Other
N/A
N/A



3: Fog Lamp Surround os
Scratched (Painted)
Over 25mm Thru Paint



4: Bonnet
Chipped
Multiple Chips



5: Screen Front
Chipped
UpTo 10mm



6: Bumper Front
Chipped
Multiple Chips



7: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint

8: Wing nsf
Cracked
Replace



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Door nsf
Scratched
Over 25mm Thru Paint



11: Other
N/A
N/A

12: Other
N/A
N/A



13: Other
N/A
N/A

14: Other
N/A
N/A



15: Door osf
 Scratched
 UpTo 25mm Thru Paint

16: Other
 N/A
 N/A



17: Seat Base Cover osf
 Holed
 Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK