

VEHICLE INSPECTION REPORT

PE63NHN

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 11/11/2013

VIN XLRAE45FF0L432566

Gearbox MANUAL

Year 2013

Body Style Box Van

Axle Combi 4x2

Mileage 799,154 Km Warranted

Service history Yes

Rear Suspension Steel

Fuel Type Diesel

MOT Due 30/06/2026

Tail Lift Cantilever

Colour RED

Cab Type DAY CAB

COLLECTED AS NON-RUNNER, CORROSION

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features


- Cruise control
- Radio/CD
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Moulding on Wing
Broken
Replace



3: Bumper Front
Rusted
Over 5mm

4: Moulding nsf Wing
Broken
Replace



5: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Other
N/A
N/A



9: Door osf
Chipped
Multiple Chips

10: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Switches And Controls
Missing
Replace



13: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		