

VEHICLE INSPECTION REPORT

SJ65GCV

Fuso Canter 7C18

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	20/01/2016	VIN	TYAFEB71ERDY08459	Axle Combi	4x2
Year	2016	Body Style	Fridge Box	Rear Doors	Barn
Mileage	283,137 Km Warranted	MOT Due	28/02/2026	Tail Lift	Column
Fuel Type	Diesel	Cab Type	DAY CAB		
Colour	WHITE	Gearbox	AUTOMATIC		


WARNING LIGHT ON DASH, TAIL LIFT IN-OP CARRIER XARIOS 600MT UNIT, STANDBY PLUG

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bonnet
Dented
Between 10mm + 30mm



3: Bumper Front
Dented
Over 30mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: A Post os
Chipped
Multiple Chips



7: A Post ns
Chipped
Multiple Chips

8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Door nsf
Dented
With Paint Damage



11: Other
N/A
N/A

12: Other
N/A
N/A



13: Other
N/A
N/A

14: Door osf
Dented
Between 10mm + 30mm



15: Other
N/A
N/A

16: Door osf
Chipped
Edge Chip



17: Door osf
Scratched
Over 25mm Thru Paint

18: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



19: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	Fault	
ABS light illuminated	OK		Service indicator light illuminated	OK	