

VEHICLE INSPECTION REPORT

PJ71NLC

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 30/12/2021

Fuel Type Diesel

Body Style MILK FLOAT

Year 2021

Colour WHITE

Gearbox MANUAL

Mileage Not Showing

VIN ZFA26300006V67029

Gears 5

NON-RUNNER, DOES NOT START, PARTS STRIPPED AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Drivers airbag
- Rear parking sensor
- Passenger airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Grill
Missing
Replace



3: Bumper Front
Dented
Over 30mm

4: Bumper Front Moulding
Missing
Replace



5: Bumper Front Moulding
Missing
Replace

6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Wing nsf
Dented
With Paint Damage

8: Wheel nsf
Dented
Over 30mm (Steel)



9: Door nsf
Dented
With Paint Damage

10: Door Mirror Assy nsf
Broken
Replace



11: Qtr Panel nsr
Dented
Over 30mm

12: Bumper Rear
Dented
Over 30mm



13: Qtr Panel osr
Dented
Over 30mm

14: Door Mirror Glass os
Missing
Replace



15: Wing osf
Dented
Over 30% Of Panel

16: Door Pad osf
Broken
Replace



17: Seat Base Cover osf
Soiled
Heavy

18: Seat Back Cover osf
Holed
Over 3mm



19: Fascia Panel
Missing
Replace

20: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	Fault		