

VEHICLE INSPECTION REPORT

PF14TXU

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details


Reg. date	14/08/2014	VIN	XLRAEL1500L437681	Gearbox	MANUAL
Year	2014	Body Style	Box Van	Axle Combi	4x2
Mileage	869,656 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/03/2026	Tail Lift	Cantilever
Colour	RED	Cab Type	DAY CAB		


COLLECTED AS NON-RUNNER, ENGINE & AD-BLUE PUMP NEED ATTN *WARNING LIGHTS ON DASH*

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Wing nsf
Chipped
Multiple Chips



5: Bumper Front
Scratched
25 to 100mm Thru Paint

6: Door Mirror Assy nsf
Broken
Replace



7: Other
N/A
N/A

8: Wing osf
Scratched
Over 25mm Thru Paint



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Bumper Rear
Rusted
Over 5mm

12: Other
N/A
N/A



13: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

14: Other
N/A
N/A



15: Seat Base Cover osf
Holed
Over 3mm

16: Seat Base Cover osf
Holed
Over 3mm



17: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average -
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK