

VEHICLE INSPECTION REPORT

PJ66BPU

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	07/11/2016	VIN	XLRAEL1500L459661	Gearbox	MANUAL
Year	2016	Body Style	Box Van	Axle Combi	4x2
Mileage	925,833 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	28/02/2026	Tail Lift	Column
Colour	RED	Cab Type	DAY CAB		

COLLECTED AS NON-RUNNER, OIL LEAK, WARNING LIGHT ON DASH



Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Number Plate Front
Broken
Replace



3: Door Mirror Assy nsf
Broken
Replace

4: Door nsf
Chipped
Multiple Chips



5: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Other
N/A
N/A

8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips

10: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint



11: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

12: Moulding osf Wing
Broken
Replace



13: Door Moulding osf
Missing
Replace

14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover nsf
 Holed
 Over 3mm

16: Other
 N/A
 N/A

Interior

Carpet Condition		Poor	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			