

VEHICLE INSPECTION REPORT

PK19JZE

Daf CF 410

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/06/2019

VIN XLRACM4100G243515

Axle Combi 8x2

Year 2019

Body Style Beavertail

Steering Combi Rear-Lift Steer

Mileage 201,190 Km Warranted

MOT Due 30/06/2026

Rear Suspension Air

Fuel Type Diesel

Cab Type DAY CAB

Colour WHITE

Gearbox AUTOMATIC

CHEESE WEDGE BODY, WINCH, SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3




OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Other
N/A
N/A

4: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



5: Door osf
Dented
Over 2 UpTo 10mm

6: Door osf
Chipped
Edge Chip



7: Door osf
Dented
Between 10mm + 30mm

8: Seat Base Cover osf
Holed
Over 3mm



9: Other
N/A
N/A

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	