

VEHICLE INSPECTION REPORT

PE17HTU

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 17/03/2017

Year 2017

Mileage 1,188,679 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G151447

Body Style Tractor Unit

Service history Yes

MOT Due 28/02/2026

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

COLLECTED AS NON-RUNNER, GEARBOX, INPUT SHAFT & RADIATOR REQUIRE ATTENTION

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4



Features

- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Broken
Replace

4: Bumper Front
Dented
With Paint Damage



5: Door nsf
Dented
With Paint Damage

6: Qtr Panel Moulding ns
Broken
Replace



7: Panel Rear
Dented
With Paint Damage

8: Door osf
Dented
Over 30mm



9: Door osf
Scratched
Over 25mm Not Thru Paint

10: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			