

VEHICLE INSPECTION REPORT

PK67VFM

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

VIN XLRTGM4100G181971

Gearbox AUTOMATIC

Year 2017

Body Style Tractor Unit

Axle Combi 6x2

Mileage 898,260 Km Warranted

Service history Yes

Steering Combi Mid-Lift

Fuel Type Diesel

MOT Due 30/11/2026

Rear Suspension Air

Colour RED

Cab Type SLEEPER CAB

WARNING LIGHT ON DASH SURROUND CAMERA SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4


Features

- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips

4: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



5: Panel Front
Cracked
Replace

6: Door nsf
Chipped
Multiple Chips



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Qtr Panel Moulding ns
Broken
Replace



9: Qtr Panel Moulding ns
Broken
Replace

10: Qtr Panel Moulding os
Broken
Replace



11: Panel Rear
Dented
With Paint Damage

12: Door osf
Chipped
Multiple Chips



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		