

VEHICLE INSPECTION REPORT

GU73FFP

Volkswagen Crafter 35 2.0 TDI 140PS

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/09/2023

Year 2023

Mileage 80,214 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZSY2R9010161

Body Style Panel Van MWB

MOT Due 24/09/2026

CAP Clean £16,300.00

CAP Average £15,100.00

CAP Below £12,950.00

Gearbox MANUAL

Gears 6

NON-RUNNER DOES NOT START OR DRIVE, ENGINE STRIPPED SIDE LOAD DOOR, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm

2: Bonnet
Dented
Over 2 UpTo 10mm



3: Sill os
Dented
With Paint Damage

4: Qtr Panel osr
Dented
With Paint Damage



5: Bumper Rear Moulding
Broken
Replace

6: Bumper Rear Moulding
Missing
Replace



7: D Post os
Dented
With Paint Damage

8: Tailgate
Dented
With Paint Damage



9: Badgedecal Rear
Missing
Replace

10: Qtr Panel nsr
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage

12: Door nsf
Dented
Over 30mm



13: Flasher Side Repeater ns
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	Fault		Gearbox 1st and Reverse Test	Fault	
Brakes	Fault		Clutch Slip Test from Static	Fault	
Turbo Boosting	Fault		Gearbox Static Gear Selection (engine running)	Fault	
Parking Brake	Fault		No Excessive Smoking	Fault	
EML light illuminated	Fault		Oil warning light illuminated	Fault	
Airbag light illuminated	Fault		Service indicator light illuminated	Fault	
ABS light illuminated	Fault				
Windows	Fault		Radio	Fault	
			Steering	Fault	