

VEHICLE INSPECTION REPORT

PE63NHB

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 18/10/2013

VIN XLRAE45FF0L431542

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 859,052 Km Warranted

MOT Due 28/02/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

COLLECTED AS NON-RUNNER, FAULT DETECTED ON MAINTENANCE TEST

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3




OSO4

Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Panel Front
Cracked
Replace

8: Door osf
Scratched
Over 25mm Thru Paint



9: Wing osf
Cracked
Replace

10: Screen Front
Cracked
Replace



11: Carpets Front
Holed
Over 3mm

12: Door Pad osf
Soiled
Heavy



13: Seat Base Cover nsf
Torn
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		