

## VEHICLE INSPECTION REPORT

**WD65OWX**

### Isuzu D-Max 2.5 TD

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

#### Details

|           |                            |             |                   |            |           |
|-----------|----------------------------|-------------|-------------------|------------|-----------|
| Reg. date | 26/11/2015                 | VIN         | MPATFS86JFT016320 | CAP Below  | £2,825.00 |
| Year      | 2015                       | Body Style  | Pickup Double Cab | Gearbox    | MANUAL    |
| Mileage   | 112,260 Miles<br>Warranted | MOT Due     | 11/07/2026        | Gears      | 6         |
| Fuel Type | Diesel                     | CAP Clean   | £5,000.00         | Axle Combi | 4x4       |
| Colour    | WHITE                      | CAP Average | £4,025.00         |            |           |

TWIN SIDE LOAD DOOR, TOW BAR, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

#### Tyres

NSF

NSR

OSF

OSR


Spare

### Features

- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


### Photos







## Condition Check



## Damage Photos



1: Roof  
Scratched  
Over 25mm Thru Paint

2: Bonnet  
Chipped  
Multiple Chips



3: Wing nsf  
Chipped  
Multiple Chips

4: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



5: Door nsf  
Chipped  
Multiple Chips

6: Qtr Panel nsr  
Chipped  
Multiple Chips



7: Qtr Panel nsr  
Chipped  
Multiple Chips

8: Qtr Panel osr  
Chipped  
Multiple Chips



9: Qtr Panel osr  
Chipped  
Multiple Chips

10: Qtr Panel osr  
Dented  
Over 30mm




11: Door osf  
Chipped  
Multiple Chips

12: Wing osf  
Chipped  
Multiple Chips



13: Bumper Front  
Scratched  
Over 100mm Thru Paint

14: Seat Base Cover osf  
Holed  
Over 3mm





15: Seat Base Cover nsf  
Soiled  
Heavy

Interior

|                       |      |                       |    |
|-----------------------|------|-----------------------|----|
| Carpet Condition      | OK   | Upholstery Condition  | OK |
| Seat Condition        | Poor | Odour                 | No |
| Engine Runs           | OK   | No Excessive Smoking  | OK |
| EML light illuminated | OK   | DPF light illuminated | OK |
| ABS light illuminated | OK   |                       |    |