

VEHICLE INSPECTION REPORT

PE17HRF

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 15/03/2017

VIN XLRTGM4100G149916

Gearbox AUTOMATIC

Year 2017

Body Style Tractor Unit

Axle Combi 6x2

Mileage 803,853 Km Warranted

Service history Yes

Steering Combi Mid-Lift

Fuel Type Diesel

MOT Due 31/10/2026

Rear Suspension Air

Colour RED

Cab Type SLEEPER CAB

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3



OSO4


Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Rusted
Over 5mm




3: Door nsf
Dented
Over 30mm

4: Door Mirror Assy nsf
Broken
Replace



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint



7: Panel Rear
Dented
With Paint Damage

8: Door osf
Dented
Over 30% Of Panel



9: Screen Front
Chipped
Over 10mm

10: Seat Base Cover osf
Holed
Over 3mm



11: Switches And Controls
Broken
Replace

12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Average
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		