

VEHICLE INSPECTION REPORT

MX09FSL

Daf LF 55.220 18 TONNE

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present	•	
Details					
Reg. date	01/03/2009	VIN	XLRAE55GF0L352752	Cab Type	DAY CAB
Year	2009	Body Style	Curtainside	Gearbox	AUTO
Mileage	865,928 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout		
Colour	RED	MOT Due	30/06/2026	•	

DAY CAB, CANTILEVER TAIL LIFT, ROLLER DOOR *COLLECTED AS NON RUNNER-COROSSION*

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OS01	OSO2	OSO3	OSO4	

Photos
















Condition Check



Damage Photos



1: Moulding osf Wing Broken Replace



2: Bumper Front Rusted Over 5mm



3: Bonnet Chipped Multiple Chips



4: General Exterior Soiled Light



5: General Exterior Soiled Light

Interior

Carpet Condition Seat Condition	OK OK		Upholstery Condition OK Odour -	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK