

VEHICLE INSPECTION REPORT

CU65CKJ

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	18/02/2016	VIN	WF0XXXTTGXFU71398	CAP Below	£2,075.00
Year	2016	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	114,054 Miles Warranted	MOT Due	01/11/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£3,500.00		
Colour	WHITE	CAP Average	£2,875.00		

RACKING, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Roof
Chipped
Multiple Chips



3: Bonnet
Chipped
Multiple Chips

4: Panel Front
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Dented
Over 30mm



7: Door nsf
Dented
With Paint Damage

8: Door Moulding nsf
Missing
Replace



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Dented
Over 30mm



11: Qtr Panel nsr
Dented
With Paint Damage

12: Qtr Panel nsr
Dented
Over 30mm



13: Qtr Panel nsr
Dented
With Paint Damage

14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

16: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



17: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

18: Door nsr
Dented
Over 30mm



19: C Post ns
Dented
With Paint Damage

20: C Post os
Scratched
Over 25mm Thru Paint




21: Door osf
Dented
With Paint Damage

22: Door osf
Scratched
Over 25mm Thru Paint



23: Wing osf
Dented
With Paint Damage

24: Wing osf
Scratched
Over 25mm Not Thru Paint



25: Door Pad osf
Soiled
Heavy

26: Seat Base Cover osf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			