

# **VEHICLE INSPECTION REPORT**

**PK67VGR** 

## **Daf CF 450**

| Non        | Runner |  |  |  |
|------------|--------|--|--|--|
| Inspection |        |  |  |  |

#### Vehicle

| Serious Damage? | No | VAT | Plus VAT |
|-----------------|----|-----|----------|
|                 |    | V5  | Present  |

#### **Details**

| Reg. date | 09/11/2017           | VIN               | XLRTGM4100G181303 | Cab Type        | SLEEPER CAB |
|-----------|----------------------|-------------------|-------------------|-----------------|-------------|
| Year      | 2017                 | Body Style        | Tractor Unit      | Gearbox         | AUTOMATIC   |
| Mileage   | 963,597 Km Warranted | Service history   | Yes               | Axle Combi      | 6x2         |
| Fuel Type | Diesel               | Service documents | Printout          | Rear Suspension | Air         |
| Colour    | RED                  | MOT Due           | 30/11/2025        |                 |             |

\*NON RUNNER - TURNS OVER WILL NOT START, ENGINE ISSUES\*\*WARNING LIGHT ON DASH\*

### **Tyres**

| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |  |
|-------|------|------|------|------|--|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |  |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |  |
|       | OS01 | OSO2 | OSO3 | OSO4 |  |

## **Features**

- Radio/CD
  Cloth seat trim
- Air conditioning
- Front electric windows
- Central locking

### **Photos**






















# **Condition Check**



# **Damage Photos**



1: Bonnet Chipped Multiple Chips



2: Bumper Front Chipped Multiple Chips



3: Bumper Front Dented Over 30mm



4: Qtr Panel Moulding ns Broken Replace



5: Qtr Panel Moulding os Scuffed (Unpainted) Over 100mm

### Interior

Carpet ConditionOKUpholstery ConditionOKSeat ConditionOKOdour-

Engine Runs Fault